

ICS Class

2B: Machinery Systems In compliance with the IMO resolution MSC.349(92) and MEPC.237(65), RO Code, Appendix 2.



The following Module 2B: Machinery Systems is based on several Example Cases of Machinery Damages. This has the purpose and objective to give a clear example on the survey check points.




MODULE 2B – Machinery Systems (Content)

- 1. Introduction
 - Numbers and Damage rates
- 2. Main diesel engine
 - Crankshaft
 - Degraded heavy fuel
 - Combustion chamber
 - Crosshead pin
 - Damage at shop test
 - Turbocharger
- 3. Propulsion Shafting
 - Coupling bolts
 - Propeller shaft
 - Propeller Breakage
 - Other notice for shafting

- 4. Aux. diesel engine
 - Connecting rod
- 5. Aux. boiler
 - Internal crack
 - Furnace Collapse
 - Exhaust gas economizer
- 6. Others
 - Fire in engine room
 - Damage due to alumina
 - Fire of feeder panel








Functional factor: corresponding to various condition of transportation

- Transportation of a large quantity: the exclusive, the huge
- A jump in fuel oil prices: the energy-saving design
- A jump in personal expense: the automatic, a small number of crew
- Low quality of fuel oil: various pretreatment equipment
- An increase of demand for conservation of environment

Safety factor: Rule of classification, strengthening the requirement of convention, such as SOLAS, etc.








Shafting (Intermediate shaft / Propeller shaft / Propeller /Bearings)


Structure of 2 stroke cycle engine



Module 2B: Machinery Systems – Rev.1 ICS Class is a member of InterMaritime© all rights reserved.


Major Damage: Numbers and Rates

Number and damage rates of ships in which damage hindered navigation




1. Introduction: Numbers and Damage Rates (Major Damage Breakdown)

Percentage by location of damage to machinery/equipment that hindered navigation




Percentage by location of damage due to diesel main engines from damage incidents that hindered navigation




Percentage by location of damage (divided to towing/speed reduction)

Damage requiring towing



Damage leading to speed reduction





2. Main diesel engine




MODULE 2B – Machinery Systems (Content)

- 1. Introduction
 - Numbers and Damage rates
- 2. Main diesel engine
 - Crankshaft
 - Degraded heavy fuel
 - Combustion chamber
 - Crosshead pin
 - Damage at shop test
 - Turbocharger
- 3. Propulsion Shafting
 - Coupling bolts
 - Propeller shaft
 - Propeller Breakage
 - Other notice for shafting

- 4. Aux. diesel engine
 - Connecting rod
- 5. Aux. boiler
 - Internal crack
 - Furnace Collapse
 - Exhaust gas economizer
- 6. Others
 - Fire in engine room
 - Damage due to alumina
 - Fire of feeder panel



Arrangement of pressure gauge



Sequence of events

ALARM

- L.O. Inlet Low Pressure
- L.O. Secondary Strainer Differential Pressure
- Confirmed the discharge pressure of M/E L.O. Pump
- 2. Pushed the pause button for M/E alarms
- 3. Continued the running

Increase

- Temperature of FWD End Main Bering
- Oil Mist Concentration

Blade Angle 0° by CPP Auto. Blade Reduction Device


Emergency Anchor and Open-up of Main Engine

Damage - Crankshaft, Main Bearing Metal, Crank Pin Metal

Damage condition



No.4 Crankpin metal



No.5 main bearing metal



No.2 main bearing metal

Crank journal at No.1 main bearing

Inspection results

Instruction of "L.O. Secondary Strainer"

When L.O. Temp. < 30 °C (High Viscosity condition): Because Auto. back-flushing will not function, manual back-flushing is required.

Actual Condition of L.O. line

- 1. L.O. Purifier had not been working for 4 days due to repair
- 2. L.O. Temp. < 30 °C

Auto. back-flushing were not carried out.

However, Manual back-flushing were not carried out.

Obstruction + Decrease of L.O. Flow

Inspection results

L.O. Inlet Pressure Low Low Alarm

M/E was not tripped.(Trip sensor problem?)

A waste cloth was stuck in the check valve on the suction of No.2 L.O. Pump.



Inspection results

L.O. Related Factors

Operational Factors


- Inoperative
- 1 L.O. Purifier
- ② Auto. Back-flushing of L.O. Secondary Strainer
- 1 L.O. Inlet Press. Low Low Alarm
- 2 L.O. Strainer Differential Press. Alarm
- ③ Waste Cloth in L.O. Pump

L.O. Degradation

- L.O. Inlet Press. decreased But -
- 1) Pause of Main Engine Alarm Device
- ② Monitor and judgment based on only Discharge Press. of L.O. Pump

Continuation of Operations

Burning of Crankshaft, Main Bearing Metal and Crank Pin Metal



Repairs

Crankshaft

MACHINING

No.	Position	Diameter [mm]			
		Original	(Reduction)	After Machining	NK Requirement
1,2,3,5,6	Journal	372	(5)	367	354.4
3,4	Pin	372	(3)	369	365.1

Bearing metal

- No.1,2,3,5,6 Main Bearing Metal: Replacement (Under Size)
- Others: Renewed (Original Size)
- No.3,4 Crank Pin Bearing Metal: Renewed (Under Size)
- Other than the above: Renewed (Original Size)

Operations and Maintenance Check Points

L.O. Factors

- Confirmation of infusions, i.e. waste cloth, in the restoration after overhauling
- Periodical and manual back-flushing in case that auto.
 back-flushing of L.O. strainer can not be used

Operational Factors

- No judgment based only L.O. Pump Discharge Press.
 (Judgment adequate L.O. flow by confirming of L.O. Inlet press.)
- Emergency treatment as a new L.O. supply at the trouble of L.O. Purifier


Repair Check Points

Temporary Repair-work Flow

- Confirmation of required diameter of crankshaft and crank-pin (ClassNK Machinery Department)
- 2. Arrangement of under sized bearing
- 3. Decision of diameter for machining
- main engine manufacturer, repairer with enough repair experience
- Confirmation of dimension measurement after machining, roundness, shaft center
- 6. Confirmation of surface hardness
- 7. Non-Destructive Test (NDT)




(Guidance for Measures to Cope with Degraded Marine Heavy Fuels)



Note: FCC means Fluid Catalytic Cracking. In order to promote cracking reaction, they use powdered form catalyst which principal ingredients are alumina, silica.

Blending of marine fuel oil

(Guidance for Measures to Cope with Degraded Marine Heavy Fuels)



Damage report

Decrease of revolution speed with increase of exhaust gas temperature in service.

Inspection Result of M/E No.4 Cylinder

Piston Crown: Burnout

Piston Ring: Breakage

Piston Skirt and Cylinder Liner: Burnout and Scratches

Temporary Repair Onboard

Damage report





Inspection results

Piston Ring

- 1. Abnormal wear (vertical scratching) on sliding surface
- 2. Uneven wear at each rings
- 3. Spherical particles (alumina and silica) in scratches on sliding surface
- 4. No Abnormalities in material composition and hardness

F.O.

FCC catalytic fines exceeding ISO standard value

Causes

Large amount of FCC catalytic fines in M/E

FCC catalytic fines enter in cylinder by fuel atomizing, and invade into clearance between piston ring and cylinder liner

Scores occur to cylinder liner inside wall(Aggressive wear)

Abnormal wear and brakeage of piston ring

Engine damage occurred due to insufficient elimination of alumina and silica at F.O. purifiers.

Attention

Pretreatment of F.O.

Marine F.O. is supplied with the assumption that pretreatment will be carried out on board.

Degraded F.O. is highly likely to cause various engine problems.

Al2O3+SiO2 (Alumina and Silica)

Amount of AL2O3+SiO3 depends on residue of FCC catalysts during oil refining process.

Damages on sliding surfaces due to high hardness

Measures

Not bunking low quality fuel oil is most effective measure (necessity of analysis of bunker oil)

Unrealistic since it is difficult to avoid bunkering low quality fuel oil completely

Therefore, steps need to be taken during operation:

- Change engine operation method (Engine side)
- Strengthen purification of fuel oil (Fuel oil side)

Operation Precaution 1 – Engine Side

- Reduce engine output;
 - Plan a reduction of mechanical loads and thermal loads
- Adjustment of cylinder coolant temperature(decide appropriate amount according to operating manual);
- Increase amount of cylinder lubricant (decide appropriate amount according to operating manual);
 - Strengthens oil film and prevents cylinder deterioration
- Raise scavenger temperature;
 - Improved ignitability of fuel due to increased temperature of compression in cylinder; (however, there will be an accompanying increase in NOx values as a result so be careful of upper limits in technical file.)
- Change fuel injection timing;
 - The earlier the fuel injection, the better the chance of covering problems of slow fuel ignition. (however, there will be an accompanying increase in NOx values as a result so be careful of upper limits in technical file.)

Main diesel engine: Degraded heavy F.O. (Example 2)

Operation Precaution 2 – Fuel Oil Side

Addition of combustion promoter

 a pro-oxidant is used to cover problems of slow ignition or incombustibility


Mixed in with normal fuel (emergency only)

- regular fuel mixed with low quality oil / degraded oil can be used continuously
- Carefully monitor engine operation and cylinder conditions

Operation Precaution 3 – Response Time

If engine operation becomes abnormal, the faster the response the better.

- responding quickly may result in only piston ring breakage.
- continued operation under abnormal burning conditions could lead to multiple cracks in the cylinder liner





Overhauling procedures

After overhauling and assembling pistons, air test was carried out.

Air leaking from bolt holes on No.1 piston crown


All cylinders were overhauled for an inspection



Condition

The followings were found:

Cracks on No.1,4,6 Piston Rods
Cracks going through bolt holes on No.1 piston rod



Causes

Fretting occurred on the contact face between No.1,4,6 Piston Rods and piston crowns

Fretting was not found on piston rod with no crack

Cracks occurred due to insufficient tightening of the fitting bolts of the piston crown

Insufficient tightening was suspected when the piston was restored during the last overhaul



Report


Crankcase oil mist alarm of main engine was activated



Damage was found upon inspection
No.B-5 Piston: Worn and scratched
Lower part of No.B-5 Cylinder Liner: Worn and scratched




Condition







Deep cut of No.B-5 Cylinder Liner



Causes

Fitting bolts on upper holding plate were loosened

Upper holding plate unfastened

Deep cuts occurred on cylinder liner and piston

Piston cooling oil also leaked

Causes

Crankcase was filled with mist of leaked cooling oil and oil mist alarm was activated.


Two years before the damage, No.B-5 cylinder was overhauled satisfactorily.

One year before the damage, the engine was overhauled satisfactorily by the manufacturer's agent.

Insufficient tightening of the fitting bolts on the upper holding plate was suspected after the overhauls



Report




Two Cracks were found at piston head supporting part of M/E during a inspection

Causes

Taper on contact surface of the inner piece was made for the relaxation of thermal stress

Fretting was occurred on this taper

Fatigue crack initiated at thread roots due to increased fluctuating stress



Fretting abrasion.

Hair crack caused by repetition of small slip at connecting part

Reason for this incident is not clarified. However it is said that mechanism is caused from adhesion by small slip and peeling off the adhesive part repeatedly.

Cause of Fretting

- Insufficient and unbalance tightening of bolt
- Manufacturing accuracy of the contact surface

On the other side, reduction of tightening force is effective for stress reduction at thread root

It comes to conflict and counter measures are difficult

Cause of Fretting



- Manufacturer raised the hardness of taper surface by surface treatment
- Overhaul of piston crown is important because it is difficult to prevent the fretting wear
- To refer to the manufacturer's service news for the criterion at the examination

Attention

In order to prevent damage in combustion chambers

Overhauling periodically combustion chambers

But, many damages were occurred by a mis-assembly at an overhauling inspection

Note

- Bolt tightening is to be carried out in accordance with the maker's manual
- Any parts are to be assembled with close attention.

Main diesel engine: Crosshead pin (Example 4 – Case 1)



Main diesel engine: Crosshead pin (Example 3 – Case 1)

Narrative

During navigation, the safety valves of crank case for No.4 & 5 Cylinder were blew up

Main engine was stopped and overhauled

No.4 Cylinder : Damage

No.5 Cylinder: No Damage

No.4 Crosshead Pin & Bearing: Burn out


No.4 Crank Case Safety Valve: Blow up

No.4 Cylinder was cut and the ship was operated under a de-rating condition Main diesel engine: Crosshead pin (Example 3 – Case 1)

Condition



No.4 Crosshead Pin



No.4 Crosshead Pin Bearing (Low. Side)

Contacting surface of housing for upper and lower bearing:

- 1) Damage by fretting (0.2~0.3 mm)
 - + Adhesion of the melted white metal
- 2) Some deeply-pressed marks due to sandwiching something

Main diesel engine: Crosshead pin (Example 3 – Case 1)


Condition

Crosshead pin bearing was tightened with sandwiching something


The fretting was occurred after loosening the tightening bolts for the bearing

- The contacting surface was worn out
- The clearance of the crosshead pin bearing exceeded the limit

During navigation, the crosshead pin hit and broke the white metal.



Main diesel engine: Crosshead pin (Example 4 – Case 2)



Main diesel engine: Crosshead pin (Example 4 – Case 2)

Incident

During navigation, the oil mist detector alarm of No.4 crank case was triggered.

The vessel sailed at reduced speed.

After arriving a port, No.4 cylinder unit was overhauled.

Crosshead Pin: Burnt Out

Crosshead Pin Metal: Burnt Out


Guide Shoe: Burnt Out

Upper Linkage Lever : Bent

The bolts to the fix pins and the plates to prevent turning were missing at the connection between the upper side and the lower side of shaking levers for supplying oil to the crosshead.

Main diesel engine: Crosshead pin (Example 4 – Case 2)

Incident



Crosshead Pin (Lower Side)



Upper Shaking Lever and Pin



Crosshead Pin Bearing (Lower Side)

Causes

Bolts for fixing pin at connecting part of shaking lever were missing.

Part of pin at connecting part of L.O. passage moved

Decreased amount of L.O. for the crosshead

Damage Occurred

Upper Shaking Lever

Connecting Part

Lower Shaking Lever

Causes


Why did the pin fixing bolts drop?

Possibility of forgetting to assemble the bolt fixing plates during the overhaul

Check During Assembly

The parts are to be confirmed in accordance with the instruction/manual of the manufacturer strictly

All parts are to be assembled with great care and attention, even if they are only very small parts



Report

After 110% load test in shop trial, visual inspection of cylinder liner was carried out from the scavenging port.

Piston crown of No.7 cylinder was stained black like coal

Damage was confirmed via opening-up inspection

Piston Crown: Abnormal Wear

Cylinder Liner: Crack


Piston Cooling Pipe: Bent

Tightening Bolts for Piston Cooling Pipe: Bent


Condition



Abnormally Worn Piston Crown



Bent Piston Cooling Pipe




Crack on Cylinder Liner



Bent Tightening Bolts for Piston Cooling Pipe

Causes



Investigation Results

Cooling oil outlet temperature of damaged cylinder: 4 degrees lower than other cylinders at 100% load operation.

Possibility of insufficient cooling

Assembly of Pistons

Tightening record of Tightening Bolts for Piston Cooling Pipe could not be found

Check points

M/E manufacturer established the procedure including improved tightening torque control of tightening bolts for piston cooling pipe.

The same damage has not occurred again.

Pay attention to not only the operating record of M/E but also assembly records of each component during the shop test.

Confirmation of quality controls of M/E manufacturer


Purpose of Turbocharger




Send large amount of air to combustion chamber in order to increase engine output




Main diesel engine: Turbocharger (Example 6)



Purpose of T/C: send large air in order to increase output Damage to T/C ⇒ lead to speed reduction






Over-run


- Breakage of turbine blade/blower
- Heat damage of rotor shaft / bearings
- Fracture of casing

















Reduced speed due to malfunction of T/C for 1 week

After the repair of T/C, a sea trial was carried out at low speed only. Normal navigation resumed.

After 1 hour and a half, turbine blade vibration was confirmed

After surging, T/C exploded as the result of overrun.

Engine room fire resulting from explosion (2 crew injured)

The fire was extinguished completely by fixed type fire extinguishing system half of an hour later

Damage Conditions



Turbocharger

Broken Engine Control Room Window



Investigation results

- Crack at No.5 & 6 Piston Ring Groove
- Scavenging space was dirty with oil



No.5 Piston Ring Groove

Investigation results

Unbalanced atomizing of No.2, 5 and 6 FO injection valve

No.5 Injection Valve



No.6 Injection Valve



Atomizing Conditions

Causes

Poor maintenance of M/E and failure to comply with manufacturer's instructions


Poor maintenance of FO injection valves and a long period of running at low speed

Unburned FO accumulated in the exhaust pipe as the result of unbalanced atomization

Engine speed was increased rapidly

Explosion occurred in the exhaust pipe

T/C over run and explosion → engine room fire




Checkpoints for turbochargers

- Periodical inspection and cleaning of T/C, M/E and air cooler
- Appropriate control of system oil
- Appropriate lubrication of cylinder oil
- Appropriate maintenance in compliance with check lists etc.







Report


While M/E was running at full speed, a loud noise was heard from starboard T/C of M/E.

Immediately reduced the revolution speed, and after 10 minutes, the engine was stopped

Damages were found at built-in LO pump, rotor shaft etc.

Reduced speed due to cutting off T/C

Reduced speed until completion of repair (1 month)




Secondary Damages



Rotor Shaft (Turbine Side)



Blower Impeller (Reduction of 5 mm in thickness)



Causes

Condition before damage: No record of any turbocharger malfunctions was found. However, four (4) months before the damage, the T/C was overhauled by the ship's crew

Slight miss alignment of rotor shaft during assembly

Breakage of drive shaft due to drive gear wear

Rotor shaft bearing burn out

Rack of L.O. supply

Vibration of rotor shaft

The damage occurred due to contact of blower impeller to casing.



Report

During navigation, noise and vibration occurred from T/C of M/E

After 1 hour, temporary repair was carried out by crews

Cleaning of each parts and replacement of turbine side bearing, labyrinth etc.

Reduced speed (T/C revolution speed: 5000rpm)

Noise and vibration continued

After 5 days, permanent repair was carried out

Damaged condition





Rotor Shaft

Turbine Blades

Causes

Evidence of abnormal running conditions was not present in the log book.

Cooling water line of casing jacket was obstructed by sludge


Insufficient cooling due to poor maintenance

- → Harmful effect for L.O.
- → Burn out of bearing



Checkpoints for turbochargers

- Built-in LO pump is running at high speed
 - → even minor failures causes serious damage.
- It is recommended that maintenance of the pump be carried out by the manufacturer.
- Damage was caused due to poor maintenance by the crew
 - e.g. It is very hard and requires a large amount of experience to know the needed whirling tolerance (maximum tolerance : 0.02 mm)



Incident

During navigation, the crew left E/R after confirming that the equipment was free of abnormalities.

M0 operation started (M/E and T/C: Rated operation)

After 2 hours, abnormal noise broke out in E/R and M/E revolution was automatically reduced


The crew found T/C stopped and Aux. blower was running automatically


The rotor shaft was sticking and the air intake socket of the blower casing was broken

Cut off T/C and reduced ship's speed to keep exhaust gas temperature below 350 degree

Damaged condition

Broken Inducer Intermediate blade






Secondary damages








Scratch on Labyrinth Disc

Causes

Corrosion pits on the intermediate blade

→ a crack developed rapidly from the resonance of the blade, and as a result, a fatigue fracture occurred.

Overhaul had been carried out 3 months prior




Second damages


5 months after the first damage incident, a second damage incident occurred

During navigation, T/C exploded suddenly without any indication

Broken Intermediate Blade







Causes

Striation → the crack was propagated by fatigue

Breakage occurred in a short period (5 months)

→ Large corrosion pit was generated

High resonance stress on the intermediate blade due to the drift of suction air.

- → The crack propagated from the corrosion pit
- → Fatigue failure occurred.


Maker recommended to replace air intake socket to new type (for decrease of resonance stress) by maker service news

But after the first damage, air intake socket was replaced with an older type of air socket

Checkpoints

Checkpoints for turbochargers

- Keep corrosive exhaust gas and sea water away from entering through the ventilation duct (in order to prevent corrosion pits at turbine blades)
- 2) Carrying out NDT on the blower side of blade
- 3) Check latest maker's service news





3. Propulsion Shafting




MODULE 2B – Machinery Systems (Content)

1. Introduction 4. Aux. diesel engine Numbers and Damage rates Connecting rod Aux. boiler 2. Main diesel engine Internal crack Crankshaft Furnace Collapse Degraded heavy fuel Exhaust gas economizer Combustion chamber - Crosshead pin 6. Others Damage at shop test Fire in engine room Turbocharger Damage due to alumina Fire of feeder panel 3. Propulsion Shafting Coupling bolts Propeller shaft Propeller Breakage Other notice for shafting

Propulsion Shafting: Coupling bolts (Example 1 – Case 1)





Propulsion Shafting: Coupling bolts (Example 1 – Case 1) Role of coupling bolts: Transmission normal torque at flange connection part; Responding to bending moment by their own strength; To avoid adhesion and looseness at flange connection part, it is necessary to tighten the bolts sufficiently.

Damage

A test of changing to ahead from astern was carried out upon entering the port.

M/E revolution hunting was found.

All coupling bolts between the crank and intermediate shafts were broken.



Fore flange of intermediate shaft



Section of bolt breakage (Crack is occurred at circumferential direction)

Damage

Material and work of coupling bolts: Good

Condition of coupling bolts on latest propeller shaft survey

Damage was not found on external examination of the bolts

After open up inspection of propeller shaft, coupling bolts were recovered by cold fitting method

There was no record of additional tightening of the bolts after the temp. of the bolts returns to the ambient temp. Therefore there is a possibility of looseness of the bolts

Torque fluctuation of torsional vibration would be principal reason of this damage

Investigation

- Torque fluctuation of torsional vibration
 - : Relatively large
- Resonance point of torsional vibration
- : 154rpm (Maximum revolution: 250rpm)
- Barred range
- : 142-167rpm
- The number of start and stop
- :Relatively many
- (The number of passing through the barred range is also relatively many)



Report

Fretting corrosion at prop. shaft and interm. shaft flanges

Magnetic particle inspection for shaft coupling bolts

Confirmation of cracks at Bolt neck end of thread

Replacement of all coupling bolts

Accident was prevented before major damage.

Investigation Results

Condition of Flange and Bolts



Fretting on connection part of flange

Crack

Caution

Occurs on roughly one (1) vessel / year.
However, if it happens, it will cause serious damage.

Confirming condition and tightness of bolt at drawing out propeller shaft at dock


Smooth avoidance of barred speed range on navigation

Caution


If cracks occur,

- the bolts must be replaced and
- 2. service schedule needs to be changed.

Check points for existing vessels



- Shortage of interference fit clearance
- 2. Misalignment of shafting




- Large torque fluctuation
- 2. Insufficient tightening

Repair/Check points


If cracks occur,

- the bolts must be replaced and
- 2. service schedule needs to be changed.


Check points for existing vessels



- Shortage of interference fit clearance
- 2. Misalignment of shafting



- 1. Large torque fluctuation
- 2. Insufficient tightening





Condition of damage

Drawing out propeller shaft at propeller shaft survey

Magnetic test at large end of cone of propeller

Finding crack with corrosion





Condition of damage

Boss of propeller: Black on contact surface of O ring due to entering of sea water

O ring: Wholly weak contact and unequal contact (especially inside)






Propeller boss

O-ring

Repair






Original diameter: 260 mm → 230 mm Required diameter: 211 mm

Repair





Original diameter: 260 mm → 230 mm

Required diameter: 211 mm


Cause

Dimension of O ring

Drawing of manufacture:

No indication of allowance for dimension of O ring

Filling grease



No filling of grease (No grease hole for this ship)


Noted point


Filling grease surely

In case of no grease hole, application of grease at following parts surely

- Space of O-ring
- Between propeller boss and propeller shaft sleeve

Adequate provision of O- ring





Report

Horizontal vibration occurred during full speed ahead running

Breakage of Propeller Blade "A"

Cut blade "C" and "D" to prevent vibration

Reduced speed operation



Damaged Condition





Fracture Surface of Blade "A"


Module 2B: Machinery Systems – Rev.1 ICS Class is a member of InterMaritime© all rights reserved.

Damaged Condition

Condition of Blade "A"



Crack Starting Point = 0.35R



Crack on Surface


"Beach Mark" = Fatigue Fracture

Causes

Cast defect around crack starting point (0.35R)

Sea water entered inside through blowholes open to the surface allowing corrosion and grinding

Minute initial cracks were caused by stress-corrosion fatigue, and the cracks were in a state of stasis for a long period.



Attention

If linearly adjacent blowholes are confirmed

Carry out PT after grinding off


If cracks are found

Possibility of cracks at the same position of other blades

Dye Penetrate Test (PT) for propeller surface


Attention

Zones for welding repairs (Part K of the Rules)



Attention

Zones for welding repairs (Part K of the Rules Highly skewed Propeller)



A: Not allowed

B: Allowed with NK approval

(Welding joint like ----- part is not allowed)

C: Allowed

Attention to welding

Procedure of welding repair for propeller

Repair plan is to be submitted and approved by NK

Repair plan:

Welding method (MIG or TIG)

Welding material (Aluminum bronze/ metal of similar composition)

Edge preparation for welding after removing defects Heat treatment

Welding by qualified welders


PT should be carried out after completing the repair



1. Attention for water-lubricated propeller shaft


Propeller shaft

- To be effectively protected from sea water
- Two lubrication method (Sea water, Oil)




Module 2B: Machinery Systems – Rev.1 ICS Class is a member of InterMaritime© all rights reserved

1. Attention for water-lubricated propeller shaft



1. Attention for water-lubricated propeller shaft



Module 2B: Machinery Systems - Rev.1 ICS Class is a member of InterMaritime© all rights reserved.

1. Attention for water-lubricated propeller shaft

Kind of propeller shaft

Propeller shaft Kind 1

A propeller shaft which is effectively protected against corrosion by sea water with an approved means

Propeller shaft kind 1A: having a water lubricated stern tube bearing

Propeller shaft kind 1B: having an oil lubricated stern tube bearing

Propeller shaft kind 1C: having an oil lubricated stern tube bearing and

monitoring, control and alarm systems for

maintaining propeller shaft bearings

Propeller shaft Kind2

A propeller shaft other than those specified in the above

1. Attention for water-lubricated propeller shaft

Check point for inspection of sea water lubricated bearing Propeller shaft dia.,d: Clearance

d≤ 230mm : 6.0mm

230mm <d≤ 305mm : 8.0mm

305mm <d : 9.5mm

In case of

- the clearance exceeds the standard value
- rapid increases of clearance at short interval

Check the crack initiation at flange part of the shaft. (increase of bending moment)

Carry out not only replacement of the S/T bearing but also measurement of the worn sleeve.

In case of rubber bearing or resin bearing

Supply sufficient cooling sea water (A shortage of cooling water occurs a carbonization of S/T bearing)

1. Attention for water-lubricated propeller shaft

Metal-Resin is accepted for use only for contact gland packing.


Reason: Metal-Resin must not be used for the part of bearings, because Resin can not endure the actual load.

Temporally repair method for propeller shaft sleeve other than a part of gland packing

- 1. Grinding the sleeve down to the required thickness.
- 2. Replace the bearing to undersize one as necessary
- 3.Replace the sleeve, in the case that the sleeve is ground over the required thickness

1. Attention for water-lubricated propeller shaft

Damage example due to insufficient use of metal resin



Intermediate shaft (oil transfer shaft for CPP) fractured at aft side flange

Propulsion Shafting: Other notice for shafting

1. Attention for water-lubricated propeller shaft

In case of sleeve replacement


- To be replaced with the original continuous sleeve
- To be replaced with the approved separate sleeve (Rubber or other synthetic resin materials with approval)

Inappropriate replacement to non-approved separate sleeves can cause a breakage of propeller shaft

Propulsion Shafting: Other notice for shafting

1. Attention for water-lubricated propeller shaft

Damage example due to insufficient use of separate type sleeves



The propeller shaft was broken during voyage. Sleeves were connected each other on the stern tube bearing

2. Attention for fitting of Keyless propeller

Position of Dial Gauge


Correct:

Dial gauge to be fitted to propeller shaft

Incorrect:

Dial gauge to be fitted to stern frame (Hull)

insufficient distance



Propulsion Shafting: Other notice for shafting

2. Attention for fitting of Keyless propeller



Condition of Corn Part after the propeller loss

Propulsion Shafting: Other notice for shafting

2. Attention for fitting of Keyless propeller

Attention of propeller fitting

Confirmation of matching mark (marking-off line)

Dial gauge should be fitted to propeller shaft.

You are recommended to use two dial gauges.

Fitting record should be made during the fitting work, and actual traveling distance should be confirmed immediately.


After fitting, propeller nut is tightened certainly.



4. Auxiliary Diesel Engine



MODULE 2B – Machinery Systems (Content)



Aux. Diesel Engine: Connecting Rod



Report

Change over to No.2 G/E single operation at harbor or anchorage.

Breakage of No.6 Piston Rod of No.2 G/E Occurred







Breakage of Piston Rod

Aux. Diesel Engine: Connecting Rod

Report

Investigation of Connecting Rod Breakage

Confirmation of Beach-Mark


Beach Mark


Scanning Electron Microscope (SEM)

Confirmation of Striation

Fatigue Fracture








Initiation Point of Crack


View from A


McGare 25. Haddinery Gystems Rev. 1 ICS Class is a member of InterMaritime© all rights reserved.


Investigation results



Causes







Direction of Maximum Principal Stress at A

Fatigue failure may occur due to small initial defect because stress around crack starting point is comparatively high.

Max principal stress in vertical direction to fracture surface

The initial crack progressed by repetitive stress fluctuation, and breakage of the rod and the bolts occurred.

Causes/Countermeasure

Seizure between the bolt and the screw hole

Insufficient tightening condition due to the seizure

Seizure is thought to have been caused by foreign particles in the screw hole

Countermeasures

- Careful cleaning of the bolts and the screw holes
- Pre-tightening test by hand in order confirm that the bolt turns smoothly.

Checkpoints

Almost all breakages of connecting rods occur due to insufficient tightening of bolts

The damage may occur up to several months after delivery

There may be no indications of the damage (e.g. LO alarm) Difficult to forecast the damage

Checkpoints

Promoting awareness at repair shipyards

Bolt tightening should be recorded as a part of the quality control.

Designation of appropriate workers and confirmation of the worker's experience


Stamping of matching mark and confirmation of tightening torque

Confirmation of screw condition (seizure etc.)

Confirmation of the appropriate tightening method from service information of engine manufacturers

Aux. Diesel Engine: Connecting Rod

Checkpoints




Countermeasures

Countermeasures in case the G/E is taken out of commission


- Confirmation of required electrical power
- At least 2 generators are required in accordance with Reg.41, Chapter II-1 of SOLAS
- Confirmation of operating condition of other generators
- 4. Installation of portable generators, if necessary




5. Auxiliary Boiler



MODULE 2B – Machinery Systems (Content)



Aux. Boiler: Internal Crack



Report


Steam leaked on the aft side of the lower parts of the boiler during M/E at MCR running.

The inside of the water drum was inspected after M/E stopped.


Cracks on the shell plate were found.

Investigation results

Condition of Damage








Investigation results

Welding of the bolts for prevention of loosening by the ship's crew

Welded Stay








Boiler Side

Causes

- Damaged part, where the tube plate is welded with the shell plate at inside of water drum, is highly stressed area.
- It is possible that cracks are initiated due to welding defects.



Thermal expansion is not absorbed efficiently by the boiler stays due to the welding of the bolts to prevent loosening.



Repairs

Repair procedure for cracks on boiler shell

- 1. PT or MT to be carried out for surface crack detection.
- 2. Stop holes to be drilled at the both ends of crack.
- 3. Edge preparation
- 4. Welding by qualified welder
- PWHT(Post Weld Heat Treatment) to be carried out, if necessary.
- PT or MT to be carried out for surface crack detection.
- 7. RT or UT to be carried out for detection of inner defects.
- 8. Hydrostatic test to be carried out.
- *1 PT: Penetration Testing
- *2 MT: Magnetic Particle Testing
- *3 RT: Radiography Testing
- *4 UT: Ultrasonic Testing

Attention for maintenance


Inspection of Water Tube Vertical Composite Boiler: Special attention to be paid to the high stressed area where the tube plate is welded with the shell plate at inside of the water drum.

Purpose of Boiler Stay:

Absorption of thermal expansion and vibration

Inadequate welding causes damage to boiler

Aux. Boiler: Furnace Collapse



Furnace collapse due to water shortage :

is caused by combustion continuation under the water low low level condition.

The main cause of occurrence of shortage of water is un-cutting of burner operation under water low low level condition due to malfunction of safety devices.




Deformation of the tube plates

After departure, crew found water leakage in furnace of boiler.



- (1)Leakage of water from smoke tube lower part
- (2)Deformation of lower tube plate
- (3)Deformation of furnace
- (4)Accumulation of scale in water side
- (5)Malfunction of feed water control system
- (6)Malfunction of low low water level burner cut system
- (7)Blockage of feed water nozzle



condition

Feed water control system:


control by signal from differential pressure transmitter through controller.

Transmitter had malfunction that continues outputting max.value of signal always.

Low low water level burner cut system by float switch

internal piece of float switch was broken/stuck.





Possible cause of damage

Malfunction of feed water system:
boiler water is not supplied when water level is low
Malfunction of float switch:
burner is not cut when water level is low low
So, combustion is continued without boiler water



Deformation/heat damage of furnace/tube/tube plate etc.


On the other hand, Accumulation of scale

Blockage of feed water nozzle

Malfunction of feed water check valve

Ship maintenance/cleaning might not function well.

Furnace collapse due to water shortage of Aux.boilers



Aux. Boiler: Furnace Collapse

Checkpoints


Furnace collapse accident

Extensive repairs are required.

Serious consequence for ship's schedule

- Water level indicators (including remote water level indicator)
- 2) Feed water control system
- 3) Low water level alarm device
- 4) F.O. shut-off device

Aux. Boiler: Exhaust gas economizer



Aux. Boiler: Exhaust gas economizer

Report

During navigation at NSR, a soot fire took place in the exhaust gas economizer and water leakage was found

Overheat and deformation were found in 80% of generating tubes



Damaged generating tubes

Repair

Temporary repairs:

All overheated generating tubes were removed and repair via by-pass was carried out.



By-pass of generating tubes

Aux. Boiler: Exhaust gas economizer

Causes

Main cause: Accumulated soot

- Adequate soot blowing
- ·Water washing

Recently, damages due to soot fire of exhaust gas economizer have decreased

Maintenance is to be carried out in compliance with manufacturers instructions

Checkpoints

Prevention measures for soot fires

- Prevention by shape and structure
 (Considering the location of pipe elbow and fittings on economizer during design stage)
- 2.Prevention by mechanical procedure (Using by-pass of exhaust gas economizer)
- Prevention by chemical procedure (Combustion additives)

Checkpoints

Prevention measures for soot fires

- 4. Prevention by maintenance
 - (Replacement of FO nozzle tips at prolonged low load operation)
- 5. Prevention by operation

(Boiler water holding time)

(Increasing soot blows)

(Exchange to high quality FO at low load operation)

6. Cleaning up of soot after soot blow

(Consideration of cleaning instrument and additional soot blow line)




6. Others



MODULE 2B – Machinery Systems (Content)







- The requirements by International Conventions (SOLAS, ILL, MARPOL, etc.) for prevention of serious accidents.
- FIRE is a serious accident having influence over the human life and the property (ship).
- In Engine Room exists high possibility of FIRE due the amount of oil and ignition sources.

Numbers of Fire in Engine Room

Year	Total number	Serious damage	Main location of cause for serious damage
2002	5	5	Return pipe of FO pump, T/C, Air pipe of FO tank
2003	2	0	-
2004	2	2	Pretreatment equipment of FO
2005	7	6	T/C, FO piping and tank for boiler, generator
2006	7	6	Exhaust manifold of M/E, Joint of FO supply piping, T/C
2007	2	1	Scavenging space of M/E
2008	7	3	T/C, Generator
2009	0	0	_
2010	3	2	Generator, Main Switch board
2011	5	3	Aux. Boiler
2012	2	2	Return pipe of FO pump, T/C
2013	6	1	LPG re-heater
2014	4	3	Generator engine (black-out), T/C,
			D.O. strainer (crew's mis-handling)

Module 2B: Machinery Systems – Rev.1 ICS Class is a member of InterMaritime© all rights reserved.

Report


Fire alarm triggered after the ship berthed

E/R was filled with black smoke that blocked a firefighting team

CO2 gas was released to the purifier room and to whole the E/R

Purifier room burnt for 4 hours

Towed for repair work



Burned Group Starter
Panel in the Purifier Room

Causes

L.O. leaked from the homogenizer

Driving shaft ball bearings were damaged due to L.O. shortage and shaft vibration occurred

F.O. leaked due to the vibration

F.O. sprayed and touched the high temperature bearings and ignited

(note) the homogenizer was installed as owner's option





Damaged Shaft of the Homogenizer

Causes

Some CO2 gas was not released (80 bottles /Total 192)


pilot lines (6mm, copper) were disconnected at 16 places





Over-tightening at installing

Disconnection due to hull vibration during voyages



E/R fire alarm sounded during voyage

Main Engine was stopped

Emergency fire pump was started

Black smoke and intense heat prevented access to E/R + the emergency fire pump was stopped

E/R burnt down and fire was extinguished 10 hours later. Three crew members died.

Damaged condition



Inside of Engine Control Room



Outside of Engine Control Room


Damaged condition

Condition of the 2nd FO Filter

Most severely burnt and its cover was completely burnt down

 Replaced with the automatic back flushing filter with aluminum cast cover after the ship was built

The Classification Society did not mention the use of aluminum cast in E/R when the ship was built





Investigation results

Condition of Exhaust Gas Expansion Joints of the M/E

No suitable enclosures or lagging

2003/07 Oil Fuel Arr. (SOLAS amendment) in force

2003/08 Class Confirmed



Lagging may have been removed after the compliance survey



Causes

Due to unknown reasons,

F.O. sprayed from 2nd F.O. filter of the M/E

The F.O. touched exhaust gas expansion joints

A fire broke out

Reasons for the expansion of the fire

Enclosures/lagging were removed from expansion joints

Cover of the 2nd F.O. filter of the M/E was made of aluminum cast which melted by flames

Leakage of large amount of F.O.

Checkpoints

Special attention must be paid to all machinery and equipment in FO pipe lines during routine inspection


Prevent FO leakage i.e. the source of ignition

Routine inspection of laggings on high temperature parts

Reduce the risk of ignition even if FO leaks

Visual inspection of fixed CO2 gas pilot lines (copper)

Prevent slack and/or disconnection due to hull vibration




Report

M/E rpm was reduced during voyage

Found that no FO was supplied to the combustion chamber of M/E


Piston rings, FO valves, cylinder liners etc. were scored.



Running M/E was suspended and the ship had to be towed

Investigation result

Small holes at temporarily repaired part of air vent pipe for FOT




Investigation result



Condition of No.2 C/H (at Annual survey before the M/E damage)







Investigation result

Analysis of FO:

-Large quantity of aluminum in No.4 FOT(P) & FO Sett./Serv.T.

Properties of alumina (general):

Particle sizes: 5-50µ

Particles adverse to combustion: 10-20µ

Density: 3.97g/cm²

 The remaining alumina was sandy like sands in an hourglass.





Left: Remaining alumina Above: FO tank with alumina (photograph of another ship)

Investigation result

Conditions after alumina mixed with FO

The finest FO filter of M/E $=50\mu$


Harmful alumina particles passed through and M/E was damaged.

The finest FO filter of $G/E = 10\mu$

No G/E was damaged as harmful alumina particles were captured.

Checkpoints

- 4) When risk of contamination of FOT by alumina etc. exists
 - FO analysis
 - Use FO from other tanks
 - Parallel use of FO purifiers
- 5) Examples of countermeasures by shipping companies
- Modification of Air Vent Pipes from SGP to STPG(Sch-80) (new ship)
- Addition of flanges to Air Vent Pipes directly above FOT (existing ship)
 - → filling Air Vent pipes with water is effective to find if a hole exists



Report

Situation: Ballasting into No.4 cargo hold was completed


Low insulation alarm was triggered

Engineer confirmed this at the engine control room

- Fire in the back of 440V feeder panel (smoke and sparks)
- Sound of water flowing & falling

Fire was extinguished with portable fire extinguisher

Damage condition








Most of electrical parts in 440V feeder panel became nonusable

Causes




The manhole cover of bilge well that located between No.4 cargo hold and void space had not been tightened enough.


When ballasting into No.4 cargo hold, ballast water invaded the void space

Causes

Ballast water invaded the void space



Causes



Checkpoints

Main cause:

Insufficient tightening of the manhole cover of bilge well

Firm confirmation before ballasting

Sounding the void space

If the sounding was done, the invading of ballast water into void space would have been confirmed.

CONCLUSIONS

- 1. In these introduced cases as serious damages, there are many accidents as cracks, fractures, breakages, fire/explosions, etc. due to compound of initial cause and others causes.
- 2. Almost half of initial cause (22 cases in 28 cases) is the mishandling (poor maintenance, mis-operation/mis-monitor, insufficient repair).
- 3. Rate of damage around combustion chamber of main engine, turbocharger is big. But the few causes are due to some problem of equipment and a lot of causes are due to low quality of fuel oil.
- 4. For minimizing the mishandling
 - Effective usage of safety management system (machinery maintenance plan)
 - Sufficient education/training to person in charge of operation and person in charge of repair
 - Close maintenance of fuel oil, lubricate oil



END

2B: Machinery Systems In compliance with the IMO resolution MSC.349(92) and MEPC.237(65), RO Code, Appendix 2.

